

**ANDHRA PRADESH EDUCATION AND WELFARE INFRASTRUCTURE
DEVELOPMENT CORPORATION**

Dr. Marri Chennareddy Bhavan, DRDA Complex, Cantonment, Vizianagaram

Pin: 535 003, Office Ph: 08922 274475.

From
Sri M. Samuel,
Executive Engineer,
A.P.E.W.I.D.C.,
Vizianagaram.

To
The Principal,
Sainik School,
Korukonda.



Re.No. SSK/KKD/2020/DB/Dt.01.07.2020.

Sir,

Sub:- APEWIDC, Vizianagaram Division - Structural Assessment of School Buildings, all Class rooms, Library, AVA Room, all laborites 8 Hostels- Buildings - Safety certificates - Report Furnished.

Ref:- 1. Your Lr. Rc. No. SSK/3022/GC/QM/2020 dt. 20.06.2020.

* * *

I invite your attention to the reference cited, the Principal, Sainik School Korukonda has requested the Executive Engineer APEWIDC., Vizianagaram to inspect and furnish the building safety certificate for the existing buildings such as all Class rooms, Library, AVA Room, all laborites 8 Hostels in the premises of Sainik School Korukonda.

Accordingly, I have inspected the all the existing buildings as mentioned above along with our field engineers on 30.06.2020, and it is informed that as per my observation the existing buildings as informed in the above reference is structurally sound at present and advised to take up the required repairs and proper maintenance to extent the life of the buildings.

Yours faithfully,

[Signature]
Executive Engineer,
A.P.E.W.I.D.C.,
Vizianagaram

PPL	<i>[Signature]</i>
VP	<i>[Signature]</i>
AQ	<i>[Signature]</i>